

Bid Addendum 03



CLARK NEXSEN

1111 Metropolitan Ave, Suite 333
Charlotte, NC 28204

Project: UNC at Charlotte:
Science Building Café Upfit

Date: March 30, 2021

Comm #: SCO ID#: 19-21440-01A
Code: 41926, Item: 306
Clark Nexsen #: 8579

Prepared by: Michael Romot, AIA

This ADDENDUM is to be a part of the contract documents and modifies and takes precedence over the original bid documents, as noted below and in any attached documents. Original items of the plans and specifications that have been modified, amended, voided or suspended through previous addendums, shall remain in effect. It is the responsibility of the Bidder to notify and/or distribute this ADDENDUM to those sub-bidders who have received prints or digital files. The Bidder is to acknowledge receipt of this ADDENDUM in the space provided on the Bid Form.

DRAWING MODIFICATIONS

- N/A

PROJECT MANUAL MODIFICATIONS

- N/A

REQUESTS FOR INFORMATION WITH RESPONSES:

No.	RFI QUESTION	RESPONSE
1.	Please provide additional detail (brand, shape, etc) for the stainless-steel posts at the G3 glass.	Basis-of-design: C.R. Laurence Co., Inc. Brushed Stainless 18" x 1" Slimline Series Round End Partition Post – Model # SBPP08EBS
2.	On page E-001 there is a reference under Equipment connection that mentions E100. There is no page E100. Please provide or clarify.	The reference to E100 should read "E-101".
3.	In the door schedule on G1003, the schedule calls for 112D Office to get a D2 door type, but the material includes GL1, please clarify what is required.	The material for door 112D should read "WD".

OWNER REMINDERS

Reminder 1: Bidders must include the **Identification of HUB Certified/Minority Business Participation** form with their bid or it will be deemed as non-responsive. At minimum, the bidder must fill in the company name at the top of the form and ensure they put zero (0) in the total value of minority business contracting will be (\$), in the event they are not listing any MBE firms on the form.

Bid Addendum 03



Reminder 2: If a signature is not signed across the seal of the sealed bid, it will be considered non-responsive and the bid will not be read.

END OF BID ADDENDA 03